

Grace (File)

P 182130Z	OUT 52316	1963 NO	OV 18 2	9 157	10 1000
FM CIA WASHDC	_		0 10 2	174	T 9 11.04 1963
TO RUCSBR/SAC OFFUTT AFB, OMAHA	. NEB				
RUCVAB/4080 STRAT WG. OL 19. RA	RKSDALE AEB	1 ^			wit a
NUCVADIZU KIS. BARKSDALE AFR. I	Δ	LH			HES TO
RUEAHQ/DIAXX					1112
RUECYG/NAVY PIC					cis d
RUWBKG/15TH AF, MARCH AFB, RIVERSIDE, CALIF					10012
RUWGAA/2AF, BARKSDALE AFB, LA				CJS CFC	
DA GRNC					CONTRACTOR OF THE PARTY OF THE
BT					PriS
SECRET CT	TE OTA 7 4 CO	~			
	1F (CIA-5-105)	9			ACL
BT SECRET CI 15TH (FOR DI); SAC (FOR DIM, B)	DACC WYOD D				#W#
THE CHOR DIM, BI	MASS KNOB, DO	JCR, DM	4) 2D	AF	
(FOR DI). FROM NATIONAL BUOTOS	DADUTA				And the second s
(FOR DI). FROM NATIONAL PHOTOGR	KAPHIC INTERF	PRETATIO	ON CENT	ER.	Cross ITT

- CAMERA B 8 WAS USED IN MISSION 3771 FLOWN ON 13 NOVEMBER 1. 1963; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.
 - 2. ORIGINAL NEGATIVE:
- THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS FAIR DUE TO THE GRAINY APPEARANCE OF THE IMAGERY.
- 9R SIDE: THE TITLING MATERIAL TRANSFERRED OR SMEARED В. INTERMITTENTLY THROUGHOUT THE MISSION. LACQUER ALONG THE TITLED EDGE APPEARS MOTTLED AND UNEVENLY APPLIED. HANDLING MARKS ARE NOTED ON FRAMES 300, 1253, 1810 THROUGH 1828. PINHOLES ARE NOTED ON FRAMES 066, 153, 300, 301, AND 773. EMULSION BLISTERS ARE PRESENT ON FRAMES 754, 1078, 1252, AND 1536. A MANUFACT-URER'S SPLICE OCCURS THROUGH FRAME 1250 WITH ASSOCIATED WRINKLING ON FRAMES 1250 THROUGH 1252. FRAMES 1810, 1811, AND 1820 CONTAIN

Declassification Review by NGA/DoD

SECRET



REPAIRED TEARS.

- C. 9L SIDE: CRIMPS AND HANDLING MARKS ARE NOTED ON FRAMES 000, 001, AND 002. PLUS DENSITY STREAKS OF VARYING LENGTHS OCCUR RANDOMLY ACROSS THE FORMAT THROUGHOUT THIS SIDE. THREE PARALLEL PLUS DENSITY STREAKS ARE PRESENT THROUGHOUT THIS SIDE ADJACENT TO INBOARD EDGE OF THE FILM. PINHOLES ARE NOTED ON FRAMES 1359, 1360, 1361, 1362, 1363 AND 1383. EMULSION LIFTS OCCUR ON FRAMES 915 AND 987. EMULSION DIGS ARE NOTED ON FRAMES 1033, 1360, AND 1333. SEVERAL BLISTERS OCCUR ON FRAME 009. THE TITLING ON FRAMES 1831 THROUGH 1847, 1849, 2120 THROUGH 2126 WAS REMOVED AND RETITLED. IN THE PROCESS OF REMOVING THE TITLING THE CLEANING SOLVENT SMEARED INTO THE FORMAT AREA ON SEVERAL FRAMES.
- D. BOTH SIDES: THE METERING IS SLIGHTLY ERRATIC WITH NO
 OVERLAPPING FORMATS NOTED. PROCESSING STREAKS ARE NOTED THROUGHOUT THIS MISSION. FORMAT FRAME FLARE APPEARS ALONG THE LEADING
 AND OUTBOARD EDGES OF THE FORMATS.
- E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS ENCOUNTERED. THERE ARE 2519 FRAMES ON EACH SIDE OF THIS MISSION.

3. POSITIVE:

- A. PI SUITABILITY IS FAIR DUE TO GROUND HAZE AND THE GRAINY APPEARANCE OF THE NEGATIVE.
 - B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURE APPROXIMATELY 75 PER CENT OF THIS MISSION. SCP-1.

SECRET

-END OF MESSAGE-

25X1